


## Oasis Verde During Construction Temperature Readings\*



Note\* The building envelope was not fully completed at the time temperatures were taken. Windows were open, garage door was not installed, attic access was open, and HVAC system was not installed.